



DUTY ON WHICH ENGAGED:

Taxiing .

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

*MULT*

*TCA/PCT  
R.170  
ICA/XA*

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Anson 6825 struck Anson 6132 whilst taxiing.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Taxiing with insufficient air pressure.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's Log Book endorsed "Carelessness" (6825).  
Disciplinary Action taken. Awarded 7 days C.B. &  
21 days R.P.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~6825 taxied into A/C 6132~~

*36 Brake Failure* (36)

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_