

CATEGORY	TYPE OF ENGINE												TYPE OF A/C												CAUSES	STAGE OF FLIGHT											
	A/C TYPE												CAUSES OF ACCIDENTS													CAUSES											
D	Harvard.												St. Hubert												MISCELLANEOUS	Harvard.											
	NAME												UNIT													HAND Q											
	RANK												COM.													INSTS.											
C	Ingalls B.J.												13 S.F.T.S.												CAUSES	LAC. 9117529											
	No.												PLACE													UNINJURED.											
	DUTY												H.Q. FILE													SERIOUS											
B	Harvard 3071												3												FLIGHT	UNINJURED.											
	TYPE A/F & ENGINE												DATE													FATAL INJURY											
	No.												TIME													CARD SERIAL NO.											
A	Harvard 3071												3												FLIGHT	UNINJURED.											
	EXTENT OF DAMAGE												M.A.													FATAL INJURY											
	REPORT FORM												H.Q. FILE													CARD SERIAL NO.											
D	A-196 7-3-42												7-3-42												FLIGHT	UNINJURED.											
	UNIT No. & DATE												1100-30-71													FATAL INJURY											
	COM. No. & DATE												1100-30-71													FATAL INJURY											
NATURE OF ACCIDENT												UNINJURED.												FATAL INJURY													

DUTY ON WHICH ENGAGED:

Navigation exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

15/155

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swerved to left after landing and ground looped.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Cross wind landing student failed to correct sufficiently.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

L. Swung

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE