

CATEGORY	TYPE OF ENGINE	TYPE OF A/C	CAUSES OF ACCIDENTS																MISCELLANEOUS CAUSES								
			AIRFRAME FAILURE								ENGINE FAILURE																
			CAUSES OF ACCIDENTS																								
			UNIT		COM.	PLACE		DATE	TIME																		
			1 E.F.T.S. Malton		1	Clairville Ont.		12-3-42	1700																		
			A/C TYPE		No.	CRASH CAT.		SE	ME	DAY	NIGHT																
			Tiger Moth		5888	B		X		X																	
			NAME			RANK	No.	DUTY	INJURIES			SERIOUS															
			Evans T.J.			TEM/SGTR	71971	FI	Uninjured.			FATAL	INJURY														
			Pickett G.A.				R122384	PP	"																		
												CARD SERIAL NO.															
			TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS																	
			T. Moth		5888	Serious				INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.											
			G. Major		85707/7802	"				215	7	70	1200	70	1200												
												45	35	45	35												
			SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT	FILE	DATE																
			A-40		12-3-42																						
			NATURE OF ACCIDENT																								

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Precautionary landing.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: *1200/PSJ/12/85* R170

COMPOSITION:

**While approaching forced landing
field lower right wing struck tree
causing A/C to nose down and crash.**

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Pilot blinded by setting sun.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

22. Collision - Obstr

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Lower right wing struck tree, A/C
nosed down & crashed.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____