

DUTY ON WHICH ENGAGED:

Sequences 3 & 9.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

LAC. Morgan was taxiing A/C into strong sun, colliding with A/C 4630 which was waiting to take-off. Damaging both propellers, upper & lower wings and lower left aileron hinge rod on 4630.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperience of LAC. Morgan to taxi into sun, and insufficient supervision by Instructor.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Sgt. Lancaster's Log Book endorsed.

(9) Collision

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C 4580 taxied into 4630.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____