

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

R170

Taxing.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

TBG/PCT

COMPOSITION:

**Aircraft landed turned off runway
wheel dropped in hole while taxiing
back to runway.**

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Carelessness on part of pilot,

10. Bad Ground

(10)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot given 72 hours detention.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Wheel of aircraft dropped in hole
breaking propeller.**

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____