

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ919

**Title:** North American Harvard Mk. II / 2 serial:AJ919 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-May-14. Harvard s/n AJ919. This accident involved 2 people. Dixon C, Jones R

**Keywords:** RAFHarvard ,AJ919,41 SFTS,41 Service Flying Training School,Aerodrome,1942-May-14,Dixon,JonesRCAF L20

**Created:** 1942-05-14

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ919>



DUTY ON WHICH ENGAGED:

I. F. Exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Crosswind swing A/C, STED oleo collapsed.

DATE:

25/10/55 ✓

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment. Cross wind,~~  
2. SWUNG

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book Endorsed:- Failed to check swing following landing. A/C ran off runway.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

34. WIC STRAIN.

34

RECORDED BY

DATE

CHECKED BY

DATE