

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil attempted to start dead motor while taxiing and collided with stationary aircraft. 8157.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Pilot failed to stop aircraft before starting engine.~~

COLLISIONS

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Admonished for carelessness. Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE