

32	JUL	31	TECH.	30	DISOB.	29	NEG/NC	28	INEXP/NC	27	MISCEL.	26	INSTRUCT.	25	FLT. CONTR.	24	OTHERS	23	PRIMARY	22	FL. CONTRS.	21	MOV. SURFS.	20	STAB. SURFS.	19	W. STRUTS	18	LAND. GEAR	17	FLOATS	16	FUSE. OR HULL	15	TAIL SWID OR W.	14	ENGINE MOUNT.	13	MISCEL.	12	UND/TD	11	PRIMARY	10	FUEL SYS.	9	COOL SYS.	8	IGNIT. SYS.	7	LUB'N SYS.	6	ENG. STR.	5	AIRSCREW A.	4	ENG. CONTRS.	3	MISCEL.	2	UND/TD	1	PRIMARY	15	HAND Q.	16	INSTS.	17	WEATHER	18	DRKMS.	19	ALG SURF.	20	OTHER	21	UND/TD	22	PRIMARY	23	TAXING	24	LANDING	25	TAKE-OFF	26	FLIGHT	27	STAT'RY	28	FATAL	29	INI.	30	3RD.	31	3RD.	32	INI.
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																					
CAUSES OF ACCIDENTS																																																																																																			
UNIT		COM.		PLACE		DATE		TIME																																																																																											
39 S.F.T.S.				Staldwyn Relief		2-6-42		0830																																																																																											
Swift Current		# 4		Landing Ground		H.Q. FILE		1300-AJ948																																																																																											
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																																																																							
Harvard II		AJ948		"C2"		X				X																																																																																									
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																																																																																					
Lister, P.M.				LAC		1247242		PP		Uninjured				FATAL INJURY																																																																																					
												CARD SERIAL NO.																																																																																							
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																							
Harvard		AJ948		Slight								INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																															
Wasp 11584/A213855 Nil												24		7		45 42		102 95																																																																																	
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																															
A588				3-6-42																																																																																															
NATURE OF ACCIDENT																																																																																																			

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

DUTY ON WHICH ENGAGED:

Solo practice on precautionary landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil stalled whilst carrying out practice of precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

RL70

DATE:

COMPOSITION:

LH/PSHM ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Error of judgment.~~

? OTHERS

⑦

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot interviewed by Chief Instructor. No disciplinary action taken.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Wing tip hit ground.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____