

DUTY ON WHICH ENGAGED:

Taxing A/C into hanger.

COURT OF INQUIRY, INVESTIGATING OFFICER

RL70

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil taxied A/C into petrol bowser. COMPOSITION:

DATE:

TCO/PCT ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Carelessness.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken against pupil. (7 days C.C.)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot taxied aircraft into petrol bowser.~~

9. COLLISIONS (9)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____