

CASPIR Aircraft Accident Cards

Serial: AJ938

Title: North American Harvard Mk. II / 2 serial:AJ938 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-June-23. Harvard s/n AJ938. This accident involved 2 people. Mathews AJ, Whiteside L

Keywords: RAFHarvard ,AJ938,41 SFTS,41 Service Flying Training School,Weyburn Aerodrome,1942-June-23,Mathews,WhitesideRCAF L20

Created: 1942-06-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ938>

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																	
CAUSES OF ACCIDENTS																															
UNIT 41 S.F.T.S.		COM. # 2		PLACE Weyburn Aerodrome										DATE 23-6-42		TIME 1910															
Weyburn, Sask		# 2		Weyburn Aerodrome										H.Q. FILE 1300-AJ938																	
A/C TYPE Harvard		No. AJ938		CRASH CAT. C3		SE		ME		DAY		NIGHT																			
NAME				RANK		NO		DUTY		INJURIES				SERIOUS																	
Mathews, A.J.				LAC		1219660		PP		Uninjured				FATAL INJURY																	
Whiteside, L.				P/O		03446		PI		Uninjured																					
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																			
Harvard		AJ938		Serious						1942		INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.													
Wasp 11574/218845		Nil		Nil								8 7		2 --		60 33															
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE																					
A67		24-6-42																													
NATURE OF ACCIDENT																															

MISCELLANEOUS CAUSES
 HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND/TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STAFFRY
 FATAL
 INJ.
 3RD.
 1ST

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

R170

Circuits and landings.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil made normal landing starboard
undercarriage collapsed.

COMPOSITION:

LUC/UDM ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Fractured top fitting of starboard
also leg.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

S. J/C. 5 FAILURE

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Starboard undercarriage collapsed.~~

35

S.S. J/C. DEFECT.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____