

## CASPIR Aircraft Accident Cards

---

**Serial:** 6211

**Title:** Avro Anson Mk. I serial:6211 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1942-June-13. They are: Anson s/n AX473, Anson I s/n 6211. This accident involved 3 people. Greenwood W, Tanner LE, Wright EH

**Keywords:** RAFAnson I,6211,41 SFTS,41 Service Flying Training School,Aerodrome,1942-June-13,Greenwood,Tanner,WrightRCAF L20

**Created:** 1942-06-13

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6211>



DUTY ON WHICH ENGAGED:

Night flying dual instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER mls  
OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 1/20/70

COMPOSITION: 1-4-70

A/C was stationary at taxiing post when A/C AX473 taxied into 6211 from rear. Pilot mistook the tail light for the light on the taxiing track.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Carelessness on the part of LAC Greenwood.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

LAC. Greenwood's Log Book will be endorsed "Carelessness."

9

9 COLLISIONS

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft AX.473 taxied into Anson 6211.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_