

CASPIR Aircraft Accident Cards

Serial: 8223

Title: Avro Anson Mk. II serial:8223 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-June-19. Anson s/n 8223. This accident involved 2 people. Mcgowan CP, Rutherford SM

Keywords: RCAFAnson ,8223, ,RCAF STN,Aerodrome,1942-June-19,Mcgowan,RutherfordRCAF L20

Created: 1942-06-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8223>

DUTY ON WHICH ENGAGED:

Wind finding exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C overshot runway and ran into deep mud causing it to nose up.

DATE:

COMPOSITION:

2/1/70

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Pilot error in landing when it was obvious that he would overshoot runway.~~

①

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilots warned of the shortness of runways at this station and the danger of overshooting the same.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft nosed up.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____