

DUTY ON WHICH ENGAGED:

Night flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Electrical system failed, landed without flaps, overshoot, went through fence.

DATE:

10/20/AFU

COMPOSITION:

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Failure of electrical system and poor landing. Error in judgment.~~

I. OVERSHOT.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Error in judgment."

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft went through fence.~~

RECORDED BY

DATE

CHECKED BY

DATE