

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ929

**Title:** North American Harvard Mk. II serial:AJ929 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-July-10. Harvard II s/n AJ929. This accident involved 1 person. Chantler RL

**Keywords:** RAFHarvard II,AJ929,41 SFTS,41 Service Flying Training School,Aerodrome,1942-July-10,ChantlerRCAF L20

**Created:** 1942-07-10

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ929>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

**Solo flying practice.**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R.170

**A/C swung due to cross-wind, port  
oleo leg collapsed.**

COMPOSITION:

*10/10/50/100/100 ✓*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~A/C swinging off runway. due to  
cross wind.~~

*2. Swung.*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**NIL.**

*2*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Port oleo leg collapsed.~~

*34. Mc Strain*

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_