

ì	· · · · · · · · · · · · · · · · · · ·	,,,,,,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,)))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	R170
)	Forced landing practice.	OR COMMANDING OFFICER'S REPORT:	<u>vr</u> to
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	✓, , ,
)	While practicing forced landing	COMPOSITION:	/ >
)	pilot opened throttle too quickly		1 410
)	engine did not respond soon enough and A/C landed wheels up.		100K/D
)	and 11,0 Idhidd wheels up.	RECOMMENDATIONS:	,
))
` }	PRIMARY CAUSE:	Nil .	
ì	Inexperience of pilot.		
, ,	Inexperience of pilot. 17. Farced Landing)
<i>)</i>	17. Forced Landing	ACTION TAKEN:)
)		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)		Log book endorsed.)
)	i)
)	di Y		,
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		,
)	Wheels up forced landing.		, , , , , , , , , , , , , , , , , , ,
)		RECORDED BY	DATE)
,			
,	R.C.A.F. FORM 120 REQ. 1247 10M—15-11-41	CHECKED BY	DATE.)
)	,,,,,, ,,,, ,,,,)))))