

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33					
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																							
CAUSES OF ACCIDENTS																																					
UNIT S.F.T.S.										COM. X										PLACE M.A.										DATE 1-7-42		TIME 1730					
Saskatoon																														H.Q. FILE 1100-77-10							
A/C TYPE Crane 1										No. 7710										CRASH CAT. C 14										SE		ME X		DAY X		NIGHT	
NAME										RANK		NO.		DUTY		INJURIES										SERIOUS											
Carr E.D.										P/O		J11562		FI		Uninjured.										FATAL	INJURY										
Geary R.M.										LAC.		R110259		PP		"																					
Fry W.										F/O		06328		Pass		"																					
TYPE A/F & ENGINE										No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																	
Crane 1										7710		Serious								INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.							
Jacobs 881/21032										Slight								31		35		6		17		10											
Jacobs 882/21031										-----								15		4		4		2		50											
SIGNAL No. & DATE										UNIT No. & DATE										COM. No. & DATE										REPORT		FILE		DATE			
D-93										2-7-42																											
NATURE OF ACCIDENT																																					

CAUSES
 MISCELLANEOUS
 FLIGHT
 STAGE OF
 TAKE-OFF
 LANDING
 TAXIING
 PRIMARY
 UND/TD
 OTHER
 ALG SURF.
 DRKNS.
 WEATHER
 INSTS.
 HAND O.
 PRIMARY

TYPE OF AC
 TYPE OF ENGINE
 CATEGORY

DUTY ON WHICH ENGAGED:

Dual instructions and ferrying control officer to R 1.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C was taking off, SWBD engine cut, A/C landed straight ahead with wheels up.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

INVESTIGATING OFFICERS REPORT.

DATE:

COMPOSITION:

2/11/50 10:00 AM - 11:00 AM

RECOMMENDATIONS:

PRIMARY CAUSE:

12. Forced Land

15

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

26. Engine trouble - accident

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____