

CASPIR Aircraft Accident Cards

Serial: 1277

Title: Oxford II serial:1277 - Crash Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-July-08. Oxford II s/n 1277. This accident involved 3 people. Morris WG, Stuart A, Till KJ

Keywords: RAF Oxford II, 1277, 34 SFTS, 34 Service Flying Training School, Aerodrome, 1942-July-08, Morris, Stuart, Till RCAF L20

Created: 1942-07-08

DUTY ON WHICH ENGAGED:

Night cross country.

COURT OF INQUIRY, INVESTIGATING OFFICER

R170

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

L4/PSS/S/EF

Ground loop causing collapse of STBD U/C. Instructor allowed aircraft to swing in a cross wind and the brake pressure failed when he applied brake to stop a ground loop.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Failure of brake pressure.~~

2. Swing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

No disciplinary action taken.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Undercarriage collapsed on a ground loop at night.~~

24. WC Strain

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____