

## CASPIR Aircraft Accident Cards

---

**Serial:** AT465

**Title:** Airspeed Oxford Mk. I serial:AT465 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-July-29. Oxford s/n AT465. This accident involved 1 person. Waugh HG

**Keywords:** RAFOxford ,AT465,35 SFTS,35 Service Flying Training School,Aerodrome,1942-July-29,WaughRCAF L20

**Created:** 1942-07-29

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AT465>



DUTY ON WHICH ENGAGED:

**Training flight.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Pupil landed with U/C retracted.**

DATE:

COMPOSITION:

*20/2001/100*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~**Faulty cockpit drill.**~~

*2. U/C Failure*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Further instruction.**

**Log Book endorsed.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~**Landed with U/C retracted.**~~

*32. U/C Drill - In Air*

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_