

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32															
PILOT																	OTHERS										AIRFRAME FAILURE										ENGINE FAILURE									
CAUSES OF ACCIDENTS																																														
UNIT 32 E.F.T.S.										COM. # 4										PLACE Aerodrome Bowden Alberta										DATE 3-7-42		TIME 0920														
A/C TYPE Stearman										No.										CRASH CAT. C1										SE		ME		DAY		NIGHT										
NAME Annear, R.										RANK LAC		No. 133919		DUTY P		INJURIES Uninjured.										SERIOUS		FATAL		INJURY																
																										CARD SERIAL No.																				
TYPE A/F & ENGINE Stearman										No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																										
																		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																				
																		1		15		15																								
SIGNAL No & DATE A236 3-7-42										UNIT No & DATE										COM. No & DATE										REPORT		FILE		DATE												
NATURE OF ACCIDENT																																														

MISCELLANEOUS
 HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 AL'G SURF.
 OTHER
 UND/TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 3RD.
 5 A

CAUSES
 FLIGHT

DUTY ON WHICH ENGAGED:

Solo practice.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Ground loop to left.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

LS/11/11

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment by inexperienced pupil.~~

2. Luung.

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE