

CASPIR Aircraft Accident Cards

Serial: FE279

Title: North American Harvard Mk. IIB serial:FE279 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-06. Harvard s/n FE279. This accident involved 1 person. Bird GW

Keywords: RAFHarvard ,FE279,41 SFTS,41 Service Flying Training School,Aerodrome,1942-August-06,BirdRCAF L20

Created: 1942-08-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE279>

DUTY ON WHICH ENGAGED:

FLYING PRACTICE

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

GROUND LOOP DAMAGING BOTH MAINPLANES,
OLEO LEGS AND FLAPS. **Bad landing.**

DATE:

COMPOSITION:

LS/PSS/VSS ✓

RECOMMENDATIONS:

NIL.

PRIMARY CAUSE:

~~Error of judgment on part of
pupil pilot.~~

R. Sewing

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~GROUND LOOP~~

3A We defect.

3A

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____