

CASPIR Aircraft Accident Cards

Serial: FE350

Title: North American Harvard Mk. IIB serial:FE350 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-07. Harvard II s/n FE350. This accident involved 2 people. Ellis V, Jones EL

Keywords: RAFHarvard II,FE350,41 SFTS,41 Service Flying Training School,Aerodrome,1942-August-07,Ellis,JonesRCAF L20

Created: 1942-08-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE350>

DUTY ON WHICH ENGAGED:

CHECK FLIGHT

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

GROUND LOOP ON LANDING

v/c damage

DATE:

R.170

COMPOSITION:

LS/PSS/E/USS ✓

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

~~ERROR OF JUDGMENT~~

E. Luung
2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Ground looped.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____