



DUTY ON WHICH ENGAGED:

Daytime navigation flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Wing tip of Anson 6735 struck star-board engine of Anson 6169 which was parked on warm-up area. 6735 was taxiing.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment. Pilot misjudged distance when taxiing.~~

9. collisions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE