

CASPIR Aircraft Accident Cards

Serial: 7643

Title: Beechcraft Expeditor 18D serial:7643 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-August-05. Beechcraft 18D s/n 7643. This accident involved 2 people. Barr GT, Smith HM

Keywords: RCAFBeechcraft 18D,7643,3 ,3 C&FF;,Aerodrome,1942-August-05,Barr,SmithRCAF L20

Created: 1942-08-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#7643>

DUTY ON WHICH ENGAGED:

Transporting personnel from Norval airport to Ottawa and return.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C landed and overshot No. 3 runway striking dirt pile and cement block at the end of runway.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Pilot landed too fast in light wind and A/C overshot runway.~~

1. Overshot

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Pilot re-checked on landing speeds on this type of A/C
Entry made in Pilot's Log Book.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck obstacles.~~

RECORDED BY

DATE

CHECKED BY

DATE