

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Transporting personnel from norval	OR COMMANDING OFFICER'S REPORT:	
airport to Ottawa and return.	R.170	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
A/C landed and overshot No. 3	COMPOSITION:	
runway striking dirt pile and	COMPOSITION:	
cement block at the end of run-	,	
way.		
	RECOMMENDATIONS:	
PRIMARY CAUSE:		
Pilot landed too fast in light		
wind and A/C overshot runway.		
1. Queishot	ACTION TAKEN:	
1. avershow	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	Pilot re-checked on landing speeds on this type of	A/0
	Entry made in Pilot's Log Book.	
\smile		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
A /C struck obstacles.		
	RECORDED BY DATE	
R.C.A.F. FORM E20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	_
		,
)