

CASPIR Aircraft Accident Cards

Serial: AS350

Title: Airspeed Oxford Mk. II serial:AS350 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-05. Oxford s/n AS350. This accident involved 1 person. Riley JG This accident had 1 fatality. Leading Aircraftman James Gerald Riley RAFVR Killed in Flying Accident service no:1483197 Oxford AS350

Keywords: RAFOxford ,AS350,35 SFTS,35 Service Flying Training School,Jackfish Lake Saskatchewan,1942-August-05,RileyRCAF L20

Created: 1942-08-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS350>

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																																				
JUL		TECH.		DISOB.		NEG NCE		INEXP NCE		MISCEL.		INSTRUCT.		FLT. CONTR.		OTHERS		PRIMARY		FL. CONTRS.		MOV. SURFS.		STAB SURFS.		W. STRUTS.		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SWD OR W.		ENGINE MOUNT.		MISCEL.		UND/TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTRS.		MISCEL.		UND/TD		PRIMARY		HAND Q.		INSTS.		WEATHER		DRKNS.		ALG SURF.		OTHER		UND/TD		PRIMARY		TAXING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		330. RNF		330. S		330. N	
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																					
CAUSES OF ACCIDENTS																																																																																																			
UNIT 35 S.F.T.S.										COM.		PLACE										DATE		TIME																																																																											
NORTH BATTLEFORD										4		JACKFISH LAKE, SASK.										5-8-42		1745																																																																											
A/C TYPE Cxford										No. AS350		CRASH CAT. A		SE		ME X		DAY X		NIGHT																																																																															
NAME										RANK		No.		DUTY		INJURIES						SERIOUS																																																																													
Riley, J.G.										LAC		1483197		PP		KILLED						FATAL INJURY																																																																													
																				1																																																																															
																				CARD SERIAL No.																																																																															
																				447																																																																															
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																							
Cxford		AS350		Totally.								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																																	
Cheetah		P172345/		-----Totally.								8 1		22 11		61 97																																																																																			
S158601/		-----Totally.																																																																																																	
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																																																																															
A505 5-8-42																																																																																																			
NATURE OF ACCIDENT																																																																																																			

DUTY ON WHICH ENGAGED:

SGLO FLYING TRAINING.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

AIRCRAFT CRASHED INTO LAKE.

DATE:

COURT OF INQUIRY

COMPOSITION:

12/20/52

RECOMMENDATIONS:

NIL

PRIMARY CAUSE:

~~DELIBERATE LOW FLYING~~

19. Out of control

19

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

CONCLUSIONS OF A.I.B.

PP DELIBERATELY ENGAGING IN UNAUTHORIZED LOW FLYING MISJUDGED HIS ALTITUDE OVER SMOOTH GLASSY SURFACE OF A LAKE AND FAILED TO LEVEL OFF BEFORE STRIKING WATER.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~ERROR OF JUDGMENT IN THAT LAKE WAS VERY CALM~~

~~AND REFLECTED SUN AND SKY GLARE.~~

42. Unauthorized Low Flying

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____