

CASPIR Aircraft Accident Cards

Serial: AS305

Title: Airspeed Oxford Mk. II serial:AS305 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-06. Oxford s/n AS305. This accident involved 4 people. Ackroyd SR, Atkinson HK, Crone AD, Herries R

Keywords: RAFOxford ,AS305,35 SFTS,35 Service Flying Training School,Holy,1942-August-06,Ackroyd,Atkinson,Crone,HerriesRCAF L20

Created: 1942-08-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS305>

DUTY ON WHICH ENGAGED:
A/C conveying engineering party to
A/C forced landed at Holy.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pilot landed on soft ground and
A/C overturned.

DATE:
COMPOSITION:

R.170
LBG/97/PESJ/XGM

RECOMMENDATIONS:

PRIMARY CAUSE:

Pilot landed on soft ground.
Error of judgment.

J. Olters

70

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C overturned.

RECORDED BY

DATE

CHECKED BY

DATE