

)	
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
PRECAUTIONARY LANDING PRACTICE	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Court of Inquiry.
Aircraft struck the ground near	DATE: 11-8-42. COMPOSITION: 14 OC for first for first
barn and caught fire, also set-	S/L W.G. Thompson No. 37 S.F.T.S.
ting fire to the barn. Aircraft	F/LT C.B. Best, DFC. No. 37 S.F.T.S.
lost height and on the last cir-	F/O G.J. Haines. No. 37 S.F.T.S.
cutt turned to the left, banked	RECOMMENDATIONS:
steeply then suddenly dove into	The danger and results of unauthorized low flying be further stressed to all flying personnel, in-
the ground with the engines on and PRIMARY CAUSE: burst into flames.	structors and pupils, and examples of this kind be b
burst into liames.	brought to the notice of all flying personnel.
ligh speed stall off a steep turn	
t a low altitude.	
20. Flew into Shound	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
M. 9 xxxx xxx	Nil
/ ()	Conclusions of A.I.B.
Australia de la Carta de Cart	Pupil pilot while deliberately engaging in un-
	authorized low flying allowed his aircraft to
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	develop a high speed stall off a steep turn. A/C crashed to the ground and burst into flames.
i rcraft dove into ground a nd	RECORDED BY DATE
ourst into flames	
30. Fire - On Shound	
R.C.A.F. FORM LZO REQ. 1247 10M-15-11-41	CHECKED BY DATE