

CASPIR Aircraft Accident Cards

Serial: AS611

Title: Airspeed Oxford Mk. I serial:AS611 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-25. Oxford s/n AS611. This accident involved 1 person. Worsford EA

Keywords: RAFOxford ,AS611,35 SFTS,35 Service Flying Training School,Aerodrome,1942-August-25,WorsfordRCAF L20

Created: 1942-08-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS611>

DUTY ON WHICH ENGAGED:

Training flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Raised U/C lever instead of flaps
lever when taxiing in after landing.
U/C retracted.

DATE:

COMPOSITION:

TUC/PCDUW/UCBT

RECOMMENDATIONS:

PRIMARY CAUSE:

Carelessness.

1. *Others*

11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~U/C retracted.~~

33. *McKillop - Ca Spauld.*

33

RECORDED BY

DATE

CHECKED BY

DATE