

		<u>,                                     </u>
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	)
Practicing solo aerobatics.	OR COMMANDING OFFICER'S REPORT: D-14.	)
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: ) Pilot blacked out during manoeuvre	DATE: COMPOSITION:	)
and on regaining vision found a/c in high speed dive. Uncertain of	COMPOSITION: /M/PSF/8/M/PM/AMS	)
) their height he used elevator con- trol trim to recover and strain buckled mainplanes at root.	RECOMMENDATIONS:	)
) PRIMARY CAUSE:		)
		)
aut of Control		)
	ACTION TAKEN:  (A) Disciplinary (B) Technical (C) Other	)
	This pilot was medically examined by station N.O. and he was found to have low blood pressure,	)
	possibly brought on by personal worries. Pilot	
	grounded until further tests made on his ability	)
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	to withstand "G" loading in aerobatics.	1
during agrada the managurage.	RECORDED BY DATE	)
)		
)	CHECKED BY DATE	)
		)