

DUTY ON WHICH ENGAGED:

Local night flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

M. J. ...

OR COMMANDING OFFICER'S REPORT:

OCO / XOR

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Collision during night take-off. Pilot of Anson 9691 took-off and struck Anson 9589 which was obstructing the flare path after ground looping. 9691 carried out a successful circuit and landing.

DATE:

COMPOSITION:

RECOMMENDATIONS:

*9589 - ...
All ...
9691 ...
all ... 9589 ...*

PRIMARY CAUSE:

*Collisions
undetected*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*awaiting decision of action taken by ...
a.t.p.*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~9691 struck 9589 when taking off.~~

RECORDED BY

DATE

CHECKED BY

DATE