

CASPIR Aircraft Accident Cards

Serial: AS775

Title: Airspeed Oxford Mk. II serial:AS775 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-September-06. Oxford II s/n AS775. This accident involved 1 person. Green GF

Keywords: RAFOxford II,AS775,35 SFTS,35 Service Flying Training School,Aerodrome,1942-September-06,GreenRCAF L20

Created: 1942-09-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS775>

DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Ground looped after overshooting,
port U/C collapsed.**

DATE:

COMPOSITION:

10/1-2/1 =

practising SE landing

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment on part of pilot.~~

Swung

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further flying instruction.

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Undercarriage collapsed.~~

U/C Strain

RECORDED BY

DATE

CHECKED BY

DATE