

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32					
TYPE OF A/C																	TYPE OF ENGINE										CATEGORY									
PILOT																	AIRFRAME FAILURE										ENGINE FAILURE									
OTHERS																	CAUSES OF ACCIDENTS										MISCELLANEOUS									
UNIT <b>36 S.F.T.S.</b>																	DATE <b>24-9-42</b>										TIME <b>1500</b>									
Penhold																	H.O. FILE <b>1300-BM764</b>										HAND O.									
A/C TYPE <b>Oxford 1</b>																	No. <b>BM764</b>										CRASH CAT. <b>A</b>									
NAME																	RANK										DUTY									
Hullah J.N.																	LAC.										1239019 PP									
INJURIES																	SERIOUS										FATAL									
Slightly Injured.																	1										CARD SERIAL NO.									
TYPE A/F & ENGINE																	No.										EXTENT OF DAMAGE									
Oxford 1 BM764																	Serial No.										DATE									
Cheetah X A158603 & A158540																	Report Form										HOURS FLOWN BY PILOTS									
Signal No. & Date																	Unit No. & Date										Com. No. & Date									
T-214 24-9-42																	Report										File									
DATE																	INST.										NIGHT									
NATURE OF ACCIDENT																	ON TYPE										TOTAL									
																	DUAL										SOLO									
																	22										24									
																	62										59									
																	LAST 6 MOS.																			

19 ( )  
 18 ( )  
 17 ( )  
 16 ( )  
 15 ( )  
 14 ( )  
 13 ( )  
 12 ( )  
 11 ( )  
 10 ( )  
 9 ( )  
 8 ( )  
 7 ( )  
 6 ( )  
 5 ( )  
 4 ( )  
 3 ( )  
 2 ( )  
 1 ( )

19 ( )  
 18 ( )  
 17 ( )  
 16 ( )  
 15 ( )  
 14 ( )  
 13 ( )  
 12 ( )  
 11 ( )  
 10 ( )  
 9 ( )  
 8 ( )  
 7 ( )  
 6 ( )  
 5 ( )  
 4 ( )  
 3 ( )  
 2 ( )  
 1 ( )

DUTY ON WHICH ENGAGED:

Solo training flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R-170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Attempted forced landing, A/C stalled into ground. Field selected for landing necessitated turn into dead engine.

DATE:

COMPOSITION:

*15/11/70*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Forced landing due to port engine failure.~~

*Forced Landing*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C stalled and struck ground.~~

*Engine Trouble - Accident*

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_