

## CASPIR Aircraft Accident Cards

---

**Serial:** FE273

**Title:** North American Harvard Mk. IIB serial:FE273 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-October-01. Harvard s/n FE273. This accident involved 1 person. Yearsley-struthers JR

**Keywords:** RAFHarvard ,FE273,41 SFTS,41 Service Flying Training School,Ralph,1942-October-01,Yearsley-struthersRCAF L20

**Created:** 1942-10-01

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE273>



DUTY ON WHICH ENGAGED:

Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C made heavy landing and port oleo leg collapsed.

DATE:

COMPOSITION:

LH/PS HH/USH ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Careless release of throttle.~~

Heavy

(H)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Port oleo leg collapsed.~~

V/C Strain

(34)

RECORDED BY

DATE

CHECKED BY

DATE