

CASPIR Aircraft Accident Cards

Serial: 2869

Title: North American Harvard Mk.II serial:2869 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-October-02. Harvard II s/n 2869. This accident involved 1 person. Battersby SH

Keywords: RCAFHarvard II,2869,14 SFTS,14 Service Flying Training School,Conn Ontario,1942-October-02,BattersbyRCAF L20

Created: 1942-10-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2869>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Solo cross country.

D-12 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

FB/PCN/ET/PS/PP/2/1954

Aircraft made wheels up forced landing. Pilot was lost and short of fuel.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error in judgment.~~

Lowrd Landing
(11)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Error in judgment".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot became lost, shortage of fuel, made wheels up forced landing.~~

Petrol shortage

(25)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____