

## CASPIR Aircraft Accident Cards

---

**Serial:** FE281

**Title:** North American Harvard Mk. IIB serial:FE281 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-October-05. Harvard s/n FE281. This accident involved 1 person. Lane RS

**Keywords:** RAFHarvard ,FE281,41 SFTS,41 Service Flying Training School,Aerodrome,1942-October-05,LaneRCAF L20

**Created:** 1942-10-05

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE281>

32	JUL	TECH.	DISOB.	INEX'NCE	MISCEL.	INSTRUCI.	FLT. CONTR.	OTHERS	PRIMARY	FL. CONTRS.	MOV. SURFS.	STAB. SURFS.	W. STRUTS	LAND GEAR	FLOATS	FUSE OR HULL	TAIL SKID OR W.	ENGINE MOUNT.	MISCEL.	UND/TD	PRIMARY	FUEL SYS.	COOL. SYS.	IGNIT. SYS.	LUBN. SYS.	ENG. STR.	AIRSCREW A.	ENG. CONTRS.	MISCEL.	UND/TD	PRIMARY	HAND Q.	INSTS.	WEATHER	DRYNS.	AL & SURF.	OTHER	UND/TD	PRIMARY	TAXYING	LANDING	TAKE OFF	FLIGHT	STRATRY	FATAL	INI.	3RD.	2	1																																																		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE										MISCELLANEOUS										CAUSES OF ACCIDENTS																																																															
UNIT 41 S.F.T.S.		COM.		PLACE		DATE 5-10-42		TIME 1300		CAUSES OF ACCIDENTS										MISCELLANEOUS																																																																															
Weyburn, Sask.		# 2		Main Aerodrome Weyburn		H. Q. FILE 1300-FE-281		CAUSES OF ACCIDENTS										MISCELLANEOUS																																																																																	
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT		MISCELLANEOUS																																																																																					
Harvard		FE281		G 2		x				x				MISCELLANEOUS																																																																																					
NAME			RANK		No.		DUTY		INJURIES				SERIOUS				MISCELLANEOUS																																																																																		
Lane, R.S.			LAC		1503625		PP		Uninjured.				FATAL		INJURY		MISCELLANEOUS																																																																																		
TYPE A/F & ENGINE										No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS								MISCELLANEOUS																																																																							
Harvard										FE 281		Serious								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS		MISCELLANEOUS																																																																							
Wasn 12004/11-12/27 NH.																		12 5		18 5		64 54				MISCELLANEOUS																																																																									
SIGNAL No & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE				MISCELLANEOUS																																																																											
A 160 5-10																								MISCELLANEOUS																																																																											
NATURE OF ACCIDENT																																																																																																			

DUTY ON WHICH ENGAGED:

Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

B.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft ground looped *on-landing*.

DATE:

COMPOSITION:

*LS/RS/WWC ✓*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperience of pilot.~~

*Swing*

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*Nil.*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C ground looped, 0.2 sec wind.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_