

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19																																																																		
P	JU	TECH.	DISOB.	NEG'NCE	INEXP'NCE	MISCEL.	INSTRUCT.	FLT. CONTR.	OTHERS	PRIMARY	FL. CONTRS.	MOV. SURFS.	STAB. SURFS.	W. SURFS.	LAND. GEAR	FLOATS	FUSE OR HULL	TAIL SWID OR W.	ENGINE MOUNT.	MISCEL.	UNDTD	PRIMARY	FUEL SYS.	COOL SYS.	IGNIT. SYS.	LUB'N SYS.	ENG. STR.	AIRSCREW A.	ENG. CONTRS.	MISCEL.	UNDTD	PRIMARY	18																																																																	
2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
TYPE OF A/C										CAUSES OF ACCIDENTS										CAUSES										STAGE OF FLIGHT																																																																				
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																				
UNIT 8 S.F.T.S.										COM. # 3					PLACE Main Aerodrome					DATE 21-10-42					TIME 0250																																																																									
Moncton, N.B.										# 3					Main Aerodrome					H.Q. FILE 1100-37-67																																																																														
A/C. TYPE Harvard II										No. 3767					CRASH CAT. C 4					SE x					ME					DAY					NIGHT x																																																															
NAME										RANK					No.					DUTY					INJURIES					SERIOUS																																																																				
Miller, R.										F/O					J9491					P					Nil					FATAL					INJURY																																																															
Waywitka, R.P.										LAC					R125985					PP					Nil																																																																									

DUTY ON WHICH ENGAGED:

Sequences 6-7-8. Night circuits.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot allowed aircraft to touch down with drift. Instructor's attempts to correct were unsuccessful and aircraft ground looped.

DATE:

COMPOSITION:

LH / PSH D/E

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error in judgment on part of pilot and trainee, coupled with carelessness.~~

*Sweeny* (2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Pilot logged.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Landing with drift.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_