

32	JU.	31	TECH.	30	DISQB.	29	NEG'NCE	28	INEXP'NCE	27	MISCEL.	26	INSTRUCT.	25	FLT CONTR.	24	OTHERS	23	PRIMARY	22	FL CONTS.	21	MOV SURFS.	20	STAB SURFS.	19	W. STRUTS	18	LAND GEAR	17	FLOATS	16	FUSE OR HULL	15	TAIL SKID OR W.	14	ENGINE MOUNT.	13	MISCEL.	12	UND TD	11	PRIMARY	10	FUEL SYS.	9	COOL SYS.	8	IGNIT. SYS.	7	LUB'N SYS.	6	ENG. STR.	5	AIRSCREW A.	4	ENG. CONTS.	3	MISCEL.	2	UND TD	1	PRIMARY	19	HAND Q.	18	INSTS.	17	WEATHER	16	DRKNS.	15	ALG SURF.	14	OTHER	13	UND TD	12	PRIMARY	11	TAXTING	10	LANDING	9	FLIGHT	8	FLIGHT	7	FATAL	6	STATRY	5	FATAL	4	INJ.	3	3RD.	2	RAF	1	
PILOT		OTHERS			AIRFRAME FAILURE										ENGINE FAILURE																																																																																						
CAUSES OF ACCIDENTS																																																																																																					
UNIT		COM.		PLACE				DATE		TIME																																																																																											
34 O.T.U.		EAC		Pennfield Ridge Aerodrome				8-10-42		1540																																																																																											
Pennfield Ridge		EAC		Pennfield Ridge Aerodrome				HQ FILE		1300-AE-658																																																																																											
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																																																																									
Ventura II		AE 658		C 7				x		x																																																																																											
NAME			RANK		No.		DUTY		INJURIES				SERIOUS																																																																																								
Chappell, P.A.J.			SGT		1318483		PP		Nil				FATAL INJURY																																																																																								
Mark, H.E.			NY SGT		414508		MAC		Nil																																																																																												
										CARD SERIAL No.																																																																																											
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																									
Ventura		AE 658		Slightly								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																																			
Drott & Whitney		102028 NAT.										38 18		11 3		106 123																																																																																					
1080001 NAT.																																																																																																					
SIGNAL No. & DATE			UNIT No. & DATE			COM. No. & DATE			REPORT			FILE			DATE																																																																																						
A 932 9-10																																																																																																					
NATURE OF ACCIDENT																																																																																																					

MISCELLANEOUS CAUSES

FLIGHT OF STAGE

DUTY ON WHICH ENGAGED:

Local day training flight - circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft swung violently to right on landing and ran on to stony ground. Aircraft ground looped.

DATE:

COMPOSITION:

LS/PSS/VSS

0.200

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperience of pilot:~~

Swing

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Stony ground looped:~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____