

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																													
JU.	TECH.	DISOB.	NEG/NC	INEXP/NC	MISCEL.	INSTRUCT.	FLT. CONTR.	OTHERS	PRIMARY	FL. CONT'S.	MOV. SURFS.	STAB. SURFS.	W. STRUTS	LAND. GEAR	FLOATS	FUSE. OR HULL	TAIL SWD OR W.	ENGINE MOUNT.	MISCEL.	UNDTD	PRIMARY	FUEL SYS.	COOL SYS.	IGNIT. SYS.	LUB'N SYS.	ENG. STR.	AIRCREW A.	ENG. CONT'S.	MISCEL.	UNDTD	PRIMARY																												
3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																														
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																													
CAUSES OF ACCIDENTS																																																											
UNIT 34 O.T.U. Pennfield Ridge.										COM. E.A.C.					PLACE Pennfield Ridge Aerodrome										DATE 30-10-48							0110																											
A/C TYPE Ventura II										No.					AE925					CRASH CAT. C 21					SE					ME					DAY					NIGHT																			
NAME										RANK					No.					DUTY					INJURIES										SERIOUS																								
Byron, J.										GB					P/O 1476473					PP					Nil										FATAL					INJURY																			
Fletcher, A.A.										NZ					SGT 411875					Obs.					Nil																																		
Mark, H.E.										NZ					SGT 414506					IC					Nil																																		
																																			CARD SERIAL No.																								
TYPE A/F & ENGINE										No.					EXTENT OF DAMAGE					REPORT FORM					SERIAL No.					DATE					HOURS FLOWN BY PILOTS																								
Ventura II										AE925					Seriously																				INST.					NIGHT					ON TYPE					TOTAL					LAST 6 MOS.				
Pratt & Whitney										263456/267456					Serious															37					20					10					37					98					167				
SIGNAL No & DATE										UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE																													
A 180										30-10																																																	
NATURE OF ACCIDENT																																																											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																												

CAUSES

STAGE OF FLIGHT

HAND.O
 INSTS.
 WEATHER
 DRKNS.
 AL-G SURF.
 OTHER
 UNDTD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STABTY
 FATAL
 INJ.
 3RD.
 5

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Night cross country training flight

DATE:

P. J. MO
7/13/67

COMPOSITION:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Taxied off the runway to avoid stranded aircraft. Took short cut across rough ground to reach taxiway and STEB wheel dropped into a hole on the ground and collapsed.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Careless~~ *Careless*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~STEB wheel dropped into hole on the ground and collapsed.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____