

DUTY ON WHICH ENGAGED:

Familiarization flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

B.170

O/M/A P/S/M/M/P

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Starboard engine failed during take-off. Struck tree top and forced landed on open field, catching fire.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Failure of STBD engine.~~

Forced Land

15

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All Polingbroke A/C grounded during P40 checks and using 100 octane gas for take-offs until carburettor jets changed to allow for 87 octane gas.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck tree top and force landed.~~

Engine Trouble - Accident

26

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____