

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																
TYPE OF A/C		TYPE OF ENGINE		CATEGORY		TYPE OF A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS				SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE																															
PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE		CAUSES OF ACCIDENTS		UNIT		COM.		PLACE		DATE		TIME		H.Q. FILE		A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																													
3 S.F.T.S.		Calgary, Alberta		# 4		Shepherd Aerodrome		31-10-42		1845		1100-81-63		Crane I		8163		C 2		x		x		NAME		RANK		No.		DUTY		INJURIES		SERIOUS																													
Corcoran, J.D.		F/O		J4328		P.		Nil		FATAL		INJURY		Kinlock, J.		CPL		R51132		Pass		Nil		CARD SERIAL No.		STAGE OF FLIGHT		HAND Q.		INSTS.		WEATHER		DRINKS.		AL G SURF.		OTHER		UND/TD		PRIMARY		TAXYING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		2RD.		3RD.		RAF	
Crane I		8163		Slight		Nil.		Nil.		Nil.		Nil.		Nil.		Nil.		Nil.		Nil.		Nil.		A 103		5-11		NATURE OF ACCIDENT		MISCELLANEOUS		UND/TD		PRIMARY		TAXYING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		2RD.		3RD.		RAF									

DUTY ON WHICH ENGAGED:

Night weather test.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft forced landed with wheels up after starboard engine failure on take-off.

DATE:

COMPOSITION:

D-14  
OFM/AOP/ES/MC/G/O/XFM

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Negligence on part of instrument mechanic in not replacing mixture control cable back in position after removing and replacing tachometer cable.~~

*Forced Land*

15

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action is being taken against R122277 LAC: Baldock, D.F., the airman responsible for the improperly secured cable.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Stbd engine failed, landed with wheels up.~~

*Engine Trouble - Accident*

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_