

CASPIR Aircraft Accident Cards

Serial: 5828

Title: de Havilland Moth, Tiger I serial:5828 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-October-02. Tiger Moth s/n 5828. This accident involved 1 person. Weir RG

Keywords: RCAF Tiger Moth ,5828,15 EFTS,15 Elementary Flying Training School,Aerodrome,1942-October-02,WeirRCAF L20

Created: 1942-10-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5828>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying.

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

~~██████~~ 20/KLP

While attempting a solo landing at night mistook boundary lights for flare path, the A/C struck fence and landed outside boundary fence.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inexperienced pupil.~~

Collisions Obstructions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

22

Three red lights will be placed 100 yards from the first flare in line with flare path.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck fence.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____