



DUTY ON WHICH ENGAGED:

Harvard -- Sequence 6-7-8.  
Yale -- Sequences 6-7-8-20.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft 3169 came in too close behind aircraft 3393 and ran into the latter before it turned off the runway,

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

DATE:

D.14.

COMPOSITION:

MULT

LCA/PSVJ ✓

RECOMMENDATIONS:

LCA/XA

Nil

PRIMARY CAUSE:

~~Gross carelessness on part of pilot P/O Warm, in that he failed to check that landing path was clear.~~

6. COLLISIONS.

⑥

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Remanded to A.O.C. for Disciplinary Action.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft 3169 and 3393 collided.~~

RECORDED BY

DATE

CHECKED BY

DATE