

CASPIR Aircraft Accident Cards

Serial: 8311

Title: Avro Anson Mk. II serial:8311 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-November-04. Anson II s/n 8311. This accident involved 1 person. Walker CJ

Keywords: RCAFAnson II,8311,16 SFTS,16 Service Flying Training School,Aerodrome,1942-November-04,WalkerRCAF L20

Created: 1942-11-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8311>

DUTY ON WHICH ENGAGED:

Night circuits and landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft swung on take-off and struck the glide path indicator.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE:

D-14

COMPOSITION:

OCO/PCM

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness on the part of the pilot.~~

12. SWUNG.

12

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Carelessness." 7 days hangar duty.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck glide path indicator.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____