

## CASPIR Aircraft Accident Cards

---

**Serial:** AS639

**Title:** Airspeed Oxford Mk. I serial:AS639 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1942-November-26. They are: Oxford s/n BF979, Oxford s/n AS639. This accident involved 1 person. Turner JR

**Keywords:** RAFOxford ,AS639,35 SFTS,35 Service Flying Training School,Aerodrome,1942-November-26,TurnerRCAF L20

**Created:** 1942-11-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS639>



DUTY ON WHICH ENGAGED:

Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

BF979 being taxied on tarmac by pupil when starboard wing collided with nose of AS639.

DATE:

COMPOSITION:

*AS  
10/1/41  
MIL/89*

RECOMMENDATIONS:

Nil.

PRIMARY CAUSE:

~~Disobedience of orders by pilot, in taxiing when aware of low brake pressure.~~

*9 COLLISIONS*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

LAC-Turner awarded 14 days C.C., and log book endorsed, for disobedience of orders.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Brakes failed in cold weather and aircraft collided.~~

*41. DISOBEDIENCE OF ORDERS.*

RECORDED BY

DATE

CHECKED BY

DATE