

31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1															
JUL	TECH.	DISOB.	NEG NCE	INEXP NCE	MISCEL.	INSTRUCT.	FLT CONTR.	OTHERS	PRIMARY	FL CONTR.	MOV. SURFS.	STAB SURFS.	W STRUTS	LAND GEAR	FLOATS	FUSE OR HULL	TAIL SKID OR W.	ENGINE MOUNT.	MISCEL.	UND/TD	PRIMARY	FUEL SYS.	COOL SYS.	IGNIT. SYS.	LUB'N SYS.	ENG STR.	AIRSCREW A.	ENG. CONTS.	MISCEL.	UND/TD															
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1														
P2	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31														
PILOT		OTHERS				AIRFRAME FAILURE										ENGINE FAILURE																													
CAUSES OF ACCIDENTS																				MISCELLANEOUS		STAGE OF FLIGHT																							
UNIT		COM.		PLACE		DATE		TIME		H.O. FILE		HAND Q.		WEATHER		DRYING.		ALG SURF		OTHER		UND/TD		PRIMARY		TAXING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		RF		RF		RF	
37 S.F.T.S.		# 4		Main Aerodrome		5-12-42		1100		1100-32-74				INSTS.																															
Calgary, Alberta														INSTR.																															
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																	
Harvard II		AJ901		D 1		C 2		x		x																																			
Harvard II		3274 P		G 2		x				x																																			
NAME		RANK		No.		DUTY		INJURIES		SERIOUS																																			
Wilson, G.E.		F/SGT		984482		FI		Nil		FATAL		INJURY																																	
Woodall, A.E.		LAC		1576344		PP		Nil																																					
										CARD SERIAL NO.																																			
										VX																																			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																									
Harvard		AJ901		Slight																																									
Wasp		213820/11549		nil.																																									
Harvard		3274		Slight																																									
Wasp		A213734/11453		NIL																																									
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																											
Q 174		2-12																																											
NATURE OF ACCIDENT																																													
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32														

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Taxiing.

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Taxiing accident. Instructor in
A/C 3274 taxied into stationary A/C
AJ901.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Gross carelessness on part of
instructor.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Instructor has been charged under Section 39 A.F.A.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~3274 taxied into AJ901 while taxiing.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____