

TYPE OF A/C		TYPE OF ENGINE		CATEGORY		STAGE OF FLIGHT		MISCELLANEOUS CAUSES		HAND Q.	
PILOT		OTHERS		AIRFRAME FAILURE		ENGINE FAILURE		CAUSES OF ACCIDENTS		UND/TD	
UNIT		COM.		PLACE		DATE		TIME		PRIMARY	
13 S.F.T.S.				Near la Chenaisie Que.		27-12-42		1115		PRIMARY	
St. Hubert, Que		# 3				H.Q. FILE		1100-32-45		PRIMARY	
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY NIGHT	
Harvard 11		3245		C 3				x		x	
NAME		RANK		No.		DUTY		INJURIES		SERIOUS	
Morrison, G.D.		F/S		R77284		P.		Nil		FATAL INJURY	
Young, D.B.		LAC		R130226		PP		Nil			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE	
Harvard 3245				Slightly							
Wasp 951/127				Slight							
HOURS FLOWN BY PILOTS		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.	
						DUAL SOLO		DUAL SOLO			
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE	
A 555 27-12											
NATURE OF ACCIDENT											

31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

TECH.
DISOB.
NEG'NCE
INEXP'NCE
MISCEL.
INSTRUCT.
FLT. CONTR.
OTHERS
PRIMARY
FL. CONTR.
MOV. SURFS.
STAB. SURFS.
W. STRUTS
LAND GEAR
FLOATS
FUSE. OR HULL
TAIL SKID OR W.
ENGINE MOUNT.
MISCEL.
UND/TD
PRIMARY
FUEL SYS.
COOL. SYS.
IGNIT. SYS.
LUB'N SYS.
ENG. STR.
AIRSCREW A.
ENG. CONTR.
MISCEL.
UND/TD
PRIMARY

19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

HAND Q.
INSTS.
WEATHER
DRKINS.
AL-G SURF.
OTHER
UND/TD
PRIMARY
TAXING
LANDING
TAKE-OFF
FLIGHT
STATIONARY
FATAL
INJ.
3RD.

32
31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

RAJ
D

MISCELLANEOUS CAUSES

DUTY ON WHICH ENGAGED:

Air to air camera gun exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While carrying out exercise engine stopped due to lack of fuel and landed with wheels up.

DATE:

D.14

COMPOSITION:

ADP

PC/PF/TS/PT/PE/PI/PO/PS

RECOMMENDATIONS:

PRIMARY CAUSE:

Error of judgement on part of instructor in delaying switching to reserve tank.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor's Log Book endorsed.

17

17 FORCED LANDING.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Engine cut out and forced landing carried out with U/C up.

25 PETROL SHORTAGE 25

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____