

CASPIR Aircraft Accident Cards

Serial: FP753

Title: Avro Anson Mk. II serial:FP753 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-December-06. Anson II s/n FP753. This accident involved 2 people. Maclaren WJ, Mondor

Keywords: RCAFAnson II,FP753,124 Sqn,124 Ferry Squadron,Kapuskasing,1942-December-06,Maclaren,MondorRCAF L20

Created: 1942-12-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP753>

DUTY ON WHICH ENGAGED:
Operational flight.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Undercarriage collapsed. Locking device failed to lock.
After refuelling the A/C was taxiing out to take-off position when the port oleo leg collapsed.

DATE:
COMPOSITION:

TUC / 1 DM / X FM
D-14

RECOMMENDATIONS:

PRIMARY CAUSE:
~~Mechanical failure.~~

8. U/C FAILURE

8

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
~~Port oleo leg collapsed while taxiing.~~

35 U/C DEFECT

35

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____