


32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT			OTHERS			AIRFRAME FAILURE										ENGINE FAILURE															
CAUSES OF ACCIDENTS																															
UNIT		12 S.F.T.S.		COM.		# 2		PLACE		Main Aerodrome		DATE				9-12-42				1110											
Brandon, Manitoba										R.O. FILE				1300-FJ164																	
A/C TYPE		Crane 1		No.		7790		CRASH CAT.		C 2		SE		NE		DAY		NIGHT													
Crane 1A				FJ164 D				C 1				x		x																	
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																	
McManamy, A.J.				LAC		R152073		PP		Nil				FATAL INJURY																	
Stanley, C.C.				LAC		R154093		PP		Nil																					
														CARD SERIAL NO.																	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																			
Crane		7790		Slight								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS													
Jacobs		21303/4167		NIL.																											
Crane		FJ164		NIL.																											
Jacobs		11/29/11/30		NIL.																											
SIGNAL No & DATE				UNIT No & DATE				COM. No. & DATE				REPORT				FILE				DATE											
CT118 9-12																															
NATURE OF ACCIDENT																															

19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
 MISCELLANEOUS CAUSES
 HAND O.
 INSTS.
 WEATHER
 DIRTY
 ALG SURE
 OTHER
 UND/TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ
 SUBJ
 INJURY



DUTY ON WHICH ENGAGED:

Taxiing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft FJ164 taxied into rear of aircraft 7790.

DATE:

COMPOSITION:

MVLT
TCA / PCT
TCA / KA
D-14

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness on part of pilot of FJ164.~~

9. COLLISIONS.

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
14 days C.B. Log book endorsement, set back two courses in accordance No. 2 T.C.I. No3/16 dated Oct. 7th, 1942.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Taxied into parked A/C 7790.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____