



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Formation flying exercise.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

D.14

Harvard II AJ699 struck Harvard II  
AJ657 while changing formation.  
While changing from No. 2 position  
to No. 3 position, pitot head of  
AJ699 struck port elevator of AJ657.

COMPOSITION:

*130/F/N ✓*

RECOMMENDATIONS:

A.J.657 abandoned by parachute and  
crashed into St. Lawrence river.

PRIMARY CAUSE:

26. Collision in the Air.

**21**

*21 Collision - A/G.*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) A/LA Bamford's Log Book endorsed and discip-  
linary action taken against him.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Gross carelessness~~ on part of A/LA  
Bamford.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_