

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Weather and runway check.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: D.14
Aircraft landed with wheels re-	COMPOSITION:
tracted. Pilot had engine trouble	LUC /UCDL/XCH
shortly after takeoff and in anxiet	•
to land failed to lower U/C. No	RECOMMENDATIONS:
signal was given from A.Control personnel.	RECOMM ENDATIONS:
personner.	Suggest Station Standing Orders (Flater)
PRIMARY CAUSE:	Suggest Station Standing Orders (Flying) be amende (Section 319, para II sub para "u") to include word
34. Whoels up landing.	"and control tender".
7 Atl	
1. acces	ACTION TAKEN:
[7]	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Nil.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Error of judgment on part of pilot. Horn failed to blow until after land	
We signal given from Control Tower.	RECORDED BY DATE
32 11/C Dillo- 1216	(34)
ET IN JUNE DO THE STATE OF THE ALL THE ALL THE	CHECKED BY DATE